

T = 4000 K

P = 0,001 ATM

Л	КО	А	Л	КО	А	Л	КО	А	Л	КО	А	Л	КО	А
224	41-10	24-02	223	51-10	30-02	222	17-08	21-02	211	11-08	13-02	210	51-08	11-02
104	41-03	11-03	103	23-01	16-03	108	96-04	21-03	111	18-04	27-03	109	12-03	29-03
110	19-03	30-03	201	18 02	13-03	105	19-01	19-03	186	10-03	38-03	206	40-04	17-03
102	24 02	16-03	187	50-04	82-03	112	23-02	26-03	107	55-02	26-03	108	15-02	28-03
203	83-01	16-03	101	83 01	14-03	180	50-02	32-03	161	25-02	74-03	207	45 01	23-03
205	28-01	14-03	202	24 02	18-03	236	81 01	28-03	137	27 01	13-03	237	41 01	65-03
238	23 01	11-02	239	14 01	19-02	240	98 00	32-02	241	88 00	52-02	154	20 01	26-03
155	98 00	81-03	204	14 02	14-03	158	59 00	10-02	157	35 00	18-02	158	23 00	30-02
159	16 00	49-02	208	61 01	19-03	242	92 01	27-03	243	46 01	52-03	244	26 01	90-03
245	16 01	15-02	246	11 01	26-02	247	79 00	42-02						

T = 4000 K

P = 0,01 ATM

Л	КО	А	Л	КО	А	Л	КО	А	Л	КО	А	Л	КО	А
230	20-09	63-01	222	18-08	21-01	211	11-07	13-01	210	52-07	11-01	104	13-02	11-02
103	76-01	16-02	108	31-03	21-02	109	38-03	30-02	110	62-03	30-02	201	18 03	13-02
105	61-01	19-02	166	32-03	35-02	102	78 02	14-02	112	74-02	25-02	107	18-01	26-02
108	50-02	26-02	203	84 00	16-02	101	27 02	13-02	160	18-01	32-02	207	45 02	24-02
205	28 00	14-02	202	24 03	16-02	236	62 02	28-02	137	87 01	12-02	237	41 02	56-02
238	24 02	88-02	239	15 02	14-01	240	97 01	22-01	241	68 01	34-01	154	64 01	26-02
155	32 01	52-02	204	14 03	14-02	158	19 01	82-02	157	11 01	13-01	158	76 00	21-01
159	53 00	32-01	208	61 02	19-02	242	93 02	25-02	243	48 02	44-02	244	25 02	70-02
245	17 02	11-01	246	11 02	18-01	247	80 01	28-01						

T = 4000 K

P = 0,03 ATM

Л	КО	А	Л	КО	А	Л	КО	А	Л	КО	А	Л	КО	А
222	52-08	62-01	211	32-07	40-01	210	15-06	32-01	104	73-02	32-02	103	13 00	47-02
106	54-03	63-02	109	66-03	88-02	110	11-02	89-02	201	53 03	40-02	105	11 00	56-02
102	13 03	39-02	112	13-01	73-02	107	31-01	78-02	108	87-02	78-02	203	25 01	47-02
101	47 02	39-02	160	28-01	93-02	207	13 03	70-02	205	84 00	42-02	202	72 03	48-02
236	24 03	83-02	137	15 02	37-02	237	12 03	16-01	238	69 02	24-01	239	43 02	37-01
240	29 02	57-01	241	20 02	85-01	154	11 02	77-02	155	58 01	15-01	204	42 03	41-02
156	32 01	22-01	157	20 01	34-01	158	13 01	53-01	159	93 00	80-01	209	18 03	56-02
242	27 03	72-02	243	14 03	12-01	244	79 02	19-01	245	49 02	30-01	246	33 02	46-01
247	24 02	68-01												

T = 4000 K

P = 0,1 ATM

Л	КО	А	Л	КО	А	Л	КО	А	Л	КО	А	Л	КО	А
211	10-06	13 90	210	49-06	10 00	103	24 00	16-01	201	17 04	13-01	105	19 00	19-01
102	24 03	13-01	112	23-01	24-01	107	58-01	26-01	203	80 01	16-01	101	85 02	13-01
207	43 03	23-01	205	27 01	14-01	202	23 04	16-01	236	78 03	27-01	137	27 02	12-01
237	39 03	50-01	238	22 03	73-01	239	14 03	11 00	240	92 02	16 00	241	65 02	24 00
154	20 02	25-01	155	10 02	46-01	204	14 04	14-01	156	58 01	68-01	157	36 01	10 00
208	58 03	18-01	242	88 03	23-01	243	44 03	40-01	244	24 03	58-01	245	16 03	87-01
246	10 03	13 00	247	76 02	19 00									

T = 4000 K

P = 0,3 ATM

Л	КО	А	Л	КО	А	Л	КО	А	Л	КО	А	Л	КО	А
211	29-08	39 00	210	14-05	32 00	103	42 00	47-01	201	48 04	39-01	105	34 00	58-01
102	43 03	38-01	203	22 02	47-01	101	15 03	39-01	207	12 04	70-01	205	76 01	41-01
202	66 04	48-01	236	22 04	82-01	137	48 02	37-01	237	11 04	14 00	238	83 03	21 00
239	39 03	30 00	240	26 03	43 00	241	18 03	60 00	154	36 02	76-01	155	18 02	13 00
204	38 04	40-01	158	10 02	19 00	208	16 04	55-01	242	25 04	68-01	243	12 04	11 00
244	89 03	18 00	245	44 03	24 00	248	33 03	34 00	247	21 03	48 00			

T = 4000 K

P = 1 ATM

Л	КО	А	Л	КО	А	Л	КО	А	Л	КО	А	Л	КО	А
210	39-05	11 01	103	77 00	18 00	201	14 05	13 00	105	63 00	19 00	102	78 03	13 00
203	64 02	18 00	101	27 03	13 00	207	35 04	23 00	205	22 02	14 00	202	19 05	18 00
236	63 04	27 00	137	89 02	12 00	237	31 04	46 00	238	18 04	64 00	239	11 04	90 00
240	74 03	13 01	241	52 03	17 01	154	65 02	25 00	155	33 02	43 00	204	11 05	13 00
208	47 04	18 00	242	71 04	22 00	243	36 04	37 00	244	19 04	52 00	245	13 04	72 00
246	65 03	10 01	247	61 03	14 01									

T = 4000 K

P = 3 ATM

Л	КО	А	Л	КО	А	Л	КО	А	Л	КО	А	Л	КО	А
201	32 05	37 00	102	14 04	38 00	203	15 03	47 00	101	48 03	39 00	207	82 04	70 00
205	51 02	41 00	202	44 05	45 00	236	15 05	81 00	137	15 03	36 00	237	74 04	14 01
238	42 04	18 01	239	26 04	25 01	240	18 04	34 01	241	12 04	45 01	154	11 03	76 00
204	28 05	39 00	208	11 05	55 00	242	17 05	68 00	243	84 04	11 01	244	46 04	15 01
245	30 04	20 01	246	20 04	27 01	247	14 04	36 01						

T = 4000 K

P = 10 ATM

Л	КО	А	Л	КО	А	Л	КО	А	Л	КО	А	Л	КО	А
201	73 05	12 01	102	25 04	13 01	203	34 03	18 01	101	89 03	13 01	207	18 05	23 01
202	10 06	15 01	236	34 05	27 01	237	17 05	44 01	238	96 04	59 01	239	60 04	79 01
240	40 04	10 02	204	59 05	13 01	208	25 05	18 01	242	38 05	22 01	243	19 05	35 01
244	10 05	47 01	245	68 04	63 01	246	45 04	83 01	247	33 04	10 02			

T = 4000 K

P = 30 ATM

Л	КО	А	Л	КО	А	Л	КО	А	Л	КО	А	Л	КО	А
201	14 06	34 01	102	44 04	38 01	203	67 03	47 01	101	15 04	39 01	207	36 05	69 01
202	20 06	42 01	236	66 06	81 01	237	33 05	13 02	238	19 05	17 02	204	12 06	37 01
208	49 05	54 01	242	74 05	64 01	243	37 05	10 02	244	20 05	14 02	245	13 05	19 02

T = 4000 K

P = 100 ATM

Л	КО	А	Л	КО	А	Л	КО	А	Л	КО	А	Л	КО	А
201	29 06	11 02	102	83 04	13 02	207	74 05	24 02	202	40 06	14 02	236	13 06	29 02
204	23 06	12 02	208	10 06	19 02	242	15 06	22 02						