

T = 11000 K

P = 0,001 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	47-08	36-07	79-07	20-07	19-08	14-08	25-05	47-05	38-05	13-05	12-04
3	14-07	11-08	24-08	59-07	57-08	42-08	60-05	85-05	58-05	26-05	23-04
5	24-07	18-08	40-08	98-07	94-08	70-08	85-05	11-04	69-05	37-05	31-04
10	47-07	36-08	79-08	20-06	19-07	14-07	13-04	16-04	85-05	60-05	44-04
20	95-07	72-06	16-05	39-08	38-07	28-07	18-04	21-04	11-04	10-04	68-04
30	14-08	11-05	24-05	59-06	57-07	42-07	21-04	25-04	13-04	14-04	77-04
100	47-08	36-05	72-05	20-05	19-06	14-06	30-04	40-04	24-04	34-04	14-03
300	14-05	11-04	21-04	59-05	57-06	42-06	36-04	58-04	48-04	83-04	26-03
A	92 02	31 08	88 08	21 08	45 08	17 09	40 08	13 08	55 03	37 02	29 09
B	24-08	18-07	40-07	98-08	94-09	70-09	15-05	49-05	80-05	23-06	17-04
1	24-08	18-07	40-07	98-08	94-09	70-09	14-05	33-05	31-05	90-06	87-05
3	71-08	54-07	12-06	29-07	28-08	21-08	38-05	63-05	49-06	17-05	17-04
5	12-07	89-07	20-08	49-07	47-08	35-08	57-05	83-05	59-05	24-05	23-04
10	24-07	18-08	40-08	98-07	94-08	70-08	94-05	12-04	73-05	39-05	33-04
20	47-07	38-08	79-08	20-06	19-07	14-07	14-04	17-04	92-05	63-05	48-04
30	71-07	54-06	12-05	29-06	28-07	21-07	17-04	20-04	10-04	84-05	68-04
100	24-08	18-05	40-05	98-08	94-07	70-07	27-04	34-04	18-04	20-04	11-03
300	71-08	54-05	11-04	29-05	28-06	21-06	34-04	50-04	32-04	49-04	19-03

T = 11000 K

P = 0,01 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	24-08	18-05	39-05	10-05	11-08	96-07	25-04	31-04	17-04	20-04	10-03
3	71-08	54-05	12-04	30-05	32-06	29-06	33-04	50-04	33-04	51-04	19-03
5	12-05	90-05	19-04	50-05	54-06	48-08	36-04	59-04	49-04	77-04	26-03
10	24-05	18-04	33-04	10-04	11-05	96-06	42-04	80-04	86-04	14-03	41-03
20	48-05	36-04	57-04	20-04	22-05	19-05	49-04	11-03	15-03	22-03	66-03
30	69-05	54-04	79-04	50-04	32-05	29-05	55-04	14-03	19-03	29-03	85-03
100	21-04	18-03	21-03	90-04	11-04	98-05	77-04	27-03	47-03	56-03	19-02
300	57-04	53-03	51-03	26-03	32-04	29-04	12-03	54-03	88-03	79-03	37-02
A	18 01	60 04	17 05	38 06	77 06	25 07	41 08	88 05	98 01	69 00	42 07
B	12-08	90-08	19-05	50-08	54-07	48-07	78-04	25-03	10-03	32-04	47-03
1	12-08	90-08	19-05	50-08	54-07	48-07	22-04	26-04	12-04	12-04	77-04
3	38-08	27-05	58-05	15-05	16-08	14-06	31-04	42-04	23-04	30-04	14-03
5	60-08	45-05	97-05	25-05	27-06	24-06	35-04	52-04	31-04	45-04	18-03
10	12-05	90-05	19-04	50-05	54-06	48-06	41-04	68-04	50-04	81-04	28-03
20	24-05	18-04	36-04	10-04	11-05	96-06	48-04	91-04	84-04	14-03	43-03
30	35-05	27-04	52-04	15-04	16-05	14-05	54-04	11-03	11-03	19-03	57-03
100	11-04	90-04	14-03	49-04	54-05	48-05	73-04	19-03	29-03	43-03	13-02
300	32-04	27-03	32-03	14-03	16-04	14-04	10-03	36-03	64-03	70-03	26-02

T = 11000 K

P = 0,03 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	11-05	84-05	18-04	48-05	58-06	58-06	39-04	64-04	46-04	71-04	25-03
3	33-05	25-04	48-04	14-04	17-05	17-05	52-04	10-03	11-03	17-03	52-03
5	54-05	42-04	72-04	24-04	29-05	29-05	60-04	14-03	16-03	24-03	75-03
10	10-04	64-04	12-03	48-04	58-05	58-05	75-04	20-03	28-03	37-03	12-02
20	20-04	17-03	20-03	90-04	12-04	12-04	98-04	31-03	42-03	52-03	19-02
30	29-04	25-03	28-03	13-03	17-04	17-04	12-03	41-03	55-03	62-03	24-02
100	82-04	82-03	76-03	40-03	58-04	58-04	20-03	79-03	11-02	86-03	51-02
300	19-03	23-02	19-02	12-02	17-03	17-03	36-03	13-02	16-02	91-03	10-01
A	39 00	13 04	34 04	78 05	14 06	41 08	60 05	11 05	23 01	16 00	70 06
B	58-08	42-05	89-05	24-05	29-06	29-06	37-03	12-02	38-03	11-03	20-02
1	58-08	42-05	89-05	24-05	29-06	29-06	38-04	56-04	30-04	42-04	16-03
3	17-05	12-04	26-04	72-05	87-06	87-06	51-04	88-04	64-04	10-03	36-03
5	28-05	21-04	42-04	12-04	14-05	14-05	59-04	11-03	94-04	15-03	50-03
10	55-05	42-04	78-04	24-04	29-05	29-05	71-04	15-03	16-03	26-03	80-03
20	11-04	84-04	14-03	48-04	58-05	58-05	89-04	22-03	27-03	40-03	13-02
30	16-04	12-03	18-03	70-04	87-05	87-05	99-04	28-03	37-03	50-03	16-02
100	48-04	42-03	46-03	22-03	29-04	29-04	16-03	54-03	81-03	78-03	35-02
300	12-03	12-02	11-02	61-03	87-04	87-04	26-03	10-02	14-02	90-03	68-02

T = 11000 K

P = 0,1 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	49-05	38-04	68-04	23-04	36-05	40-05	72-04	18-03	16-03	23-03	77-03
3	14-04	11-03	17-03	68-04	11-04	12-04	11-03	31-03	35-03	45-03	16-02
5	22-04	19-03	25-03	11-03	18-04	20-04	14-03	43-03	49-03	56-03	22-02
10	42-04	37-03	42-03	20-03	36-04	40-04	20-03	63-03	75-03	72-03	34-02
20	75-04	74-03	74-03	39-03	72-04	80-04	28-03	91-03	11-02	85-03	52-02
30	10-03	11-02	10-02	58-03	11-03	12-03	35-03	11-02	13-02	89-03	66-02
100	25-03	34-02	28-02	18-02	36-03	40-03	66-03	19-02	19-02	91-03	14-01
300	46-03	88-02	68-02	53-02	11-02	12-02	13-02	28-02	22-02	91-03	31-01
A	87-01	28-03	71-03	14-05	32-05	59-05	73-04	12-04	47-00	34-01	12-06
B	25-05	19-04	40-04	11-04	19-05	20-05	16-02	54-02	14-02	42-03	89-02
1	25-05	19-04	39-04	11-04	19-05	20-05	67-04	12-03	94-04	15-03	51-03
3	74-05	56-04	10-03	34-04	56-05	60-05	96-04	22-03	22-03	33-03	11-02
5	12-04	94-04	16-03	57-04	96-05	10-04	12-03	29-03	32-03	44-03	15-02
10	23-04	19-03	27-03	11-03	19-04	20-04	16-03	42-03	53-03	61-03	23-02
20	44-04	37-03	46-03	21-03	38-04	40-04	21-03	65-03	82-03	77-03	36-02
30	63-04	56-03	63-03	31-03	58-04	60-04	26-03	79-03	10-02	84-03	46-02
100	17-03	18-02	17-02	97-03	19-03	20-03	48-03	14-02	17-02	91-03	95-02
300	36-03	52-02	42-02	26-02	58-03	60-03	10-02	23-02	21-02	91-03	20-01

T = 11000 K

P = 0,3 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	16-04	13-03	21-03	86-04	17-04	21-04	16-03	40-03	41-03	49-03	20-02
3	44-04	39-03	48-03	24-03	52-04	62-04	28-03	78-03	81-03	74-03	39-02
5	68-04	64-03	72-03	39-03	87-04	10-03	36-03	10-02	10-02	83-03	52-02
10	12-03	13-02	13-02	75-03	17-03	21-03	52-03	14-02	14-02	90-03	80-02
20	20-03	24-02	22-02	15-02	35-03	42-03	76-03	20-02	18-02	91-03	12-01
30	26-03	35-02	31-02	22-02	52-03	62-03	11-02	23-02	19-02	91-03	16-01
100	49-03	99-02	79-02	69-02	17-02	21-02	17-02	34-02	22-02	91-03	37-01
300	66-03	22-01	16-01	19-01	51-02	61-02	34-02	47-02	22-02	91-03	81-01
A	25-01	76-02	18-03	34-04	44-04	11-05	14-04	22-03	13-00	94-02	21-05
B	89-05	66-04	14-03	43-04	94-05	10-04	58-02	18-01	44-02	14-02	30-01
1	86-05	66-04	12-03	43-04	94-05	10-04	13-03	29-03	26-03	37-03	13-02
3	24-04	20-03	30-03	13-03	28-04	32-04	21-03	55-03	59-03	63-03	27-02
5	39-04	33-03	44-03	21-03	47-04	53-04	27-03	70-03	80-03	75-03	36-02
10	72-04	65-03	78-03	40-03	94-04	10-03	38-03	10-02	12-02	86-03	55-02
20	13-03	13-02	13-02	77-03	19-03	21-03	55-03	15-02	15-02	90-03	84-02
30	18-03	19-02	18-02	11-02	28-03	32-03	90-03	18-02	17-02	91-03	11-01
100	40-03	60-02	50-02	36-02	94-03	10-02	13-02	29-02	21-02	91-03	24-01
300	61-03	15-01	12-01	10-01	28-02	31-02	26-02	41-02	22-02	91-03	54-01

T = 11000 K

P = 1 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	54-04	49-03	64-03	37-03	99-04	12-03	44-03	11-02	98-03	78-03	50-02
3	13-03	14-02	16-02	10-02	30-03	37-03	88-03	19-02	15-02	91-03	10-01
5	19-03	23-02	24-02	16-02	50-03	52-03	11-02	24-02	18-02	91-03	14-01
10	30-03	44-02	41-02	32-02	99-03	12-02	15-02	31-02	20-02	91-03	22-01
20	44-03	79-02	70-02	63-02	20-02	24-02	22-02	39-02	22-02	91-03	35-01
30	52-03	11-01	94-02	92-02	29-02	37-02	29-02	43-02	22-02	91-03	47-01
100	68-03	25-01	20-01	28-01	95-02	12-01	52-02	61-02	22-02	91-03	11-00
300	69-03	43-01	35-01	70-01	26-01	33-01	10-01	86-02	22-02	91-03	23-00
A	64-02	19-02	41-02	87-03	75-03	19-04	19-03	29-02	31-01	24-02	36-04
B	34-04	25-03	51-03	19-03	55-04	63-04	21-01	69-01	16-01	48-02	11-00
1	31-04	26-03	38-03	19-03	55-04	63-04	33-03	75-03	74-03	70-03	35-02
3	82-04	74-03	93-03	53-03	16-03	19-03	59-03	14-02	13-02	87-03	68-02
5	12-03	12-02	14-02	87-03	27-03	32-03	94-03	19-02	16-02	90-03	95-02
10	21-03	24-02	25-02	17-02	55-03	63-03	12-02	25-02	19-02	91-03	14-01
20	34-03	46-02	43-02	33-02	11-02	13-02	16-02	32-02	21-02	91-03	23-01
30	43-03	67-02	60-02	49-02	16-02	19-02	24-02	37-02	22-02	91-03	31-01
100	64-03	18-01	14-01	15-01	54-02	62-02	38-02	52-02	22-02	91-03	72-01
300	69-03	35-01	27-01	43-01	16-01	18-01	72-02	74-02	22-02	91-03	16-00

T = 11000 K

P = 3 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	14-03	15-02	19-02	14-02	50-03	61-03	12-02	24-02	16-02	91-03	12-01
3	30-03	42-02	44-02	40-02	15-02	18-02	21-02	38-02	20-02	91-03	23-01
5	40-03	66-02	67-02	65-02	25-02	30-02	28-02	43-02	22-02	91-03	36-01
10	64-02	12-01	11-01	12-01	49-02	60-02	38-02	52-02	22-02	91-03	58-01
20	64-03	19-01	17-01	23-01	97-02	12-01	55-02	64-02	22-02	91-03	97-01
30	68-03	25-01	22-01	33-01	14-01	17-01	70-02	73-02	22-02	91-03	13 00
100	69-03	45-01	39-01	69-01	42-01	51-01	14-01	10-01	22-02	91-03	29 00
300	69-03	60-01	53-01	18 00	95-01	12 00	25-01	13-01	22-02	91-03	55 00
A	19-02	55 01	10 02	15 03	14 03	38 03	34 02	50 01	86-02	72-03	73 03
B	11-03	60-03	16-02	73-03	29-03	32-03	67-01	22 00	48-01	15-01	35 00
1	89-04	79-03	11-02	71-03	29-03	32-03	99-03	18-02	14-02	88-03	84-02
3	21-03	23-02	27-02	20-02	86-03	97-03	15-02	30-02	19-02	91-03	18-01
5	30-03	38-02	41-02	34-02	14-02	16-02	24-02	38-02	21-02	91-03	24-01
10	45-03	72-02	70-02	66-02	28-02	32-02	30-02	45-02	22-02	91-03	38-01
20	58-03	13-01	12-01	13-01	58-02	64-02	41-02	55-02	22-02	91-03	63-01
30	64-03	18-01	16-01	19-01	84-02	95-02	52-02	84-02	22-02	91-03	85-01
100	69-03	37-01	30-01	57-01	27-01	30-01	11-01	92-02	22-02	91-03	20 00
300	69-03	65-01	45-01	14 00	70-01	62-01	21-01	12-01	22-02	91-03	43 00

T = 11000 K

P = 10 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	34-03	50-02	59-02	62-02	30-02	37-02	33-02	48-02	21-02	91-03	35-01
3	56-03	12-01	13-01	18-01	88-02	11-01	57-02	66-02	22-02	91-03	80-01
5	84-03	18-01	20-01	28-01	14-01	18-01	78-02	78-02	22-02	91-03	12 00
10	68-03	28-01	28-01	51-01	27-01	33-01	12-01	96-02	22-02	91-03	19 00
20	69-03	40-01	38-01	89-01	48-01	61-01	18-01	11-01	22-02	91-03	31 00
30	69-03	47-01	44-01	12 00	66-01	84-01	22-01	12-01	22-02	91-03	40 00
100	69-03	63-01	57-01	24 00	14 00	18 00	34-01	14-01	22-02	91-03	74 00
300	69-03	65-01	58-01	32 00	20 00	28 00	39-01	14-01	22-02	91-03	97 00
A	52-03	14 01	21 01	28 02	28 02	60 02	46 01	63 00	22-02	19-03	12 03
B	42-03	29-02	57-02	34-02	17-02	20-02	23 00	74 00	16 00	51-01	12 01
1	25-03	28-02	36-02	33-02	17-02	20-02	26-02	41-02	20-02	91-03	23-01
3	47-03	77-02	86-02	96-02	52-02	81-02	44-02	58-02	22-02	91-03	51-01
5	57-03	12-01	12-01	18-01	85-02	10-01	58-02	69-02	22-02	91-03	75-01
10	66-03	20-01	20-01	30-01	17-01	20-01	90-02	86-02	22-02	91-03	13 00
20	68-03	32-01	29-01	56-01	32-01	38-01	14-01	10-01	22-02	91-03	22 00
30	69-03	39-01	35-01	80-01	46-01	55-01	18-01	12-01	22-02	91-03	26 00
100	69-03	58-01	52-01	19 00	12 00	14 00	32-01	14-01	22-02	91-03	81 00
300	69-03	65-01	57-01	30 00	18 00	25 00	38-01	14-01	22-02	91-03	92 00

T = 11000 K

P = 30 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	59-03	14-01	17-01	25-01	14-01	17-01	93-02	87-02	22-02	91-03	11 00
3	68-03	29-01	31-01	83-01	37-01	46-01	18-01	12-01	22-02	91-03	24 00
5	69-03	38-01	39-01	94-01	56-01	70-01	23-01	13-01	22-02	91-03	34 00
10	69-03	50-01	50-01	15 00	93-01	12 00	31-01	14-01	22-02	91-03	51 00
20	69-03	60-01	58-01	22 00	14 00	18 00	35-01	14-01	22-02	91-03	71 00
30	69-03	63-01	58-01	26 00	16 00	22 00	37-01	14-01	22-02	91-03	82 00
100	69-03	65-01	58-01	32 00	20 00	29 00	39-01	14-01	22-02	91-03	10 01
300	69-03	65-01	58-01	32 00	20 00	29 00	39-01	14-01	22-02	91-03	10 01
A	15-03	37 00	48 00	62 01	47 01	12 02	74 00	94-01	54-03	52-04	25 02
B	15-02	94-02	18-01	14-01	86-02	10-01	67 00	22 01	47 00	15 00	36 01
1	50-03	64-02	11-01	13-01	84-02	98-02	67-02	76-02	22-02	91-03	68-01
3	66-03	20-01	22-01	38-01	24-01	28-01	13-01	10-01	22-02	91-03	16 00
5	68-03	29-01	30-01	60-01	38-01	46-01	18-01	12-01	22-02	91-03	24 00
10	69-03	42-01	41-01	11 00	69-01	84-01	26-01	14-01	22-02	91-03	39 00
20	69-03	54-01	50-01	18 00	11 00	14 00	34-01	14-01	22-02	91-03	59 00
30	69-03	60-01	54-01	22 00	14 00	18 00	37-01	14-01	22-02	91-03	72 00
100	69-03	65-01	58-01	32 00	20 00	28 00	39-01	14-01	22-02	91-03	97 00
300	69-03	65-01	58-01	32 00	20 00	29 00	39-01	14-01	22-02	91-03	10 01

T = 11000 K

P = 100 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	69-03	34-01	39-01	10 00	71-01	10 00	30-01	14-01	22-02	91-03	40 00
3	69-03	64-01	54-01	21 00	14 00	20 00	36-01	14-01	22-02	91-03	71 00
5	69-03	61-01	57-01	26 00	17 00	24 00	38-01	14-01	22-02	91-03	85 00
10	69-03	65-01	58-01	31 00	20 00	28 00	39-01	14-01	22-02	91-03	98 00
20	69-03	65-01	58-01	32 00	20 00	29 00	39-01	14-01	22-02	91-03	10 01
30	69-03	65-01	58-01	32 00	20 00	29 00	39-01	14-01	22-02	91-03	10 01
100	69-03	65-01	58-01	32 00	20 00	29 00	39-01	14-01	22-02	91-03	10 01
300	69-03	65-01	58-01	32 00	20 00	29 00	39-01	14-01	22-02	91-03	10 01
A	35-04	80-01	85-01	10 01	69 00	14 01	79-01	11-01	11-03	11-04	34 01
B	63-02	36-01	62-01	77-01	58-01	87-01	21 01	71 01	15 01	56 00	12 02
1	68-03	25-01	29-01	68-01	50-01	74-01	25-01	13-01	22-02	91-03	29 00
3	69-03	47-01	47-01	16 00	12 00	17 00	36-01	14-01	22-02	91-03	59 00
5	69-03	56-01	52-01	22 00	15 00	22 00	38-01	14-01	22-02	91-03	76 00
10	69-03	63-01	57-01	29 00	19 00	27 00	39-01	14-01	22-02	91-03	93 00
20	69-03	65-01	58-01	32 00	20 00	29 00	39-01	14-01	22-02	91-03	99 00
30	69-03	65-01	58-01	32 00	20 00	29 00	39-01	14-01	22-02	91-03	10 01
100	69-03	65-01	58-01	32 00	20 00	29 00	39-01	14-01	22-02	91-03	10 01
300	69-03	65-01	58-01	32 00	20 00	29 00	39-01	14-01	22-02	91-03	10 01