

T = 12000 K

P = 0,001 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	29-08	20-07	38-07	11-07	12-08	97-09	11-05	30-05	58-05	19-05	12-04
3	68-08	59-07	11-06	32-07	38-08	29-08	31-05	88-05	80-05	31-05	21-04
5	14-07	98-07	19-06	54-07	60-08	48-08	48-05	95-05	96-05	40-05	28-04
10	29-07	20-06	38-06	11-06	12-07	97-08	83-05	14-04	12-04	60-05	41-04
20	58-07	39-06	75-06	22-06	24-07	19-07	13-04	20-04	15-04	94-05	59-04
30	88-07	59-06	11-05	32-06	36-07	29-07	17-04	24-04	16-04	12-04	73-04
100	29-06	20-05	38-05	11-05	12-06	97-07	30-04	43-04	26-04	30-04	14-03
300	88-06	59-05	10-04	32-05	36-06	29-06	41-04	86-04	44-04	89-04	24-03
A	92 02	33 06	96 08	28 08	64 08	30 09	90 08	38 08	32 04	27 03	52 09
B	14-08	98-08	19-07	54-08	60-09	48-09	60-06	20-05	13-04	46-05	20-04
1	14-08	98-08	19-07	54-08	60-09	48-09	60-06	18-05	46-05	15-05	86-05
3	43-08	29-07	56-07	16-07	18-08	14-08	17-05	45-05	70-05	24-05	16-04
5	72-08	49-07	94-07	27-07	30-08	24-08	28-05	65-05	82-05	30-05	21-04
10	14-07	98-07	19-06	54-07	60-08	48-08	52-05	10-04	10-04	42-05	30-04
20	29-07	20-06	38-06	11-06	12-07	97-08	91-05	15-04	13-04	63-05	44-04
30	43-07	29-06	56-06	16-06	18-07	14-07	12-04	18-04	14-04	82-05	54-04
100	14-06	98-06	19-05	54-06	60-07	48-07	24-04	34-04	21-04	19-04	10-03
300	43-06	29-05	56-05	16-05	18-06	14-06	37-04	55-04	33-04	42-04	18-03

T = 12000 K

P = 0,01 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	22-06	15-05	28-05	81-06	89-07	77-07	27-04	37-04	22-04	24-04	12-03
3	66-06	45-05	84-05	24-05	27-08	23-06	40-04	80-04	39-04	58-04	21-03
5	11-05	75-05	14-04	41-05	44-06	38-06	45-04	76-04	54-04	88-04	29-03
10	22-05	15-04	26-04	81-05	89-06	77-06	51-04	99-04	87-04	16-03	45-03
20	42-05	30-04	46-04	16-04	18-05	15-05	59-04	13-03	15-03	28-03	72-03
30	63-05	45-04	63-04	24-04	27-05	23-05	65-04	16-03	20-03	38-03	96-03
100	19-04	15-03	16-03	75-04	89-05	77-05	89-04	30-03	52-03	86-03	22-02
300	50-04	44-03	41-03	22-03	27-04	23-04	13-03	58-03	11-02	14-02	44-02
A	12 01	42 04	12 05	34 06	64 06	37 07	83 06	22 06	37 02	34 01	59 07
B	11-06	75-06	14-05	41-06	44-07	38-07	47-04	15-03	15-03	55-04	41-03
1	11-06	75-06	14-05	41-06	44-07	38-07	22-04	30-04	18-04	15-04	87-04
3	33-06	22-05	42-05	12-05	13-08	12-06	35-04	52-04	28-04	35-04	18-03
5	55-06	37-05	70-05	20-05	22-06	19-06	41-04	65-04	38-04	52-04	21-03
10	11-05	75-05	14-04	41-05	44-06	38-06	49-04	87-04	57-04	92-04	31-03
20	22-05	15-04	27-04	81-05	89-06	77-06	57-04	11-03	90-04	16-03	48-03
30	32-05	22-04	39-04	12-04	13-05	12-05	64-04	14-03	12-03	23-03	63-03
100	10-04	75-04	11-03	40-04	44-05	38-05	86-04	23-03	31-03	59-03	14-02
300	29-04	22-03	25-03	12-03	13-04	12-04	12-03	40-03	72-03	12-02	30-02

T = 12000 K

P = 0,03 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	14-05	93-05	17-04	52-05	63-06	64-08	51-04	92-04	62-04	10-03	34-03
3	40-05	28-04	45-04	15-04	19-05	19-05	67-04	15-03	14-03	26-03	70-03
5	65-05	46-04	70-04	26-04	31-05	32-05	78-04	19-03	20-03	36-03	10-02
10	12-04	92-04	12-03	52-04	63-05	64-05	98-04	28-03	37-03	61-03	16-02
20	24-04	16-03	21-03	98-04	12-04	13-04	13-03	43-03	60-03	94-03	26-02
30	34-04	28-03	29-03	14-03	19-04	19-04	15-03	56-03	80-03	12-02	35-02
100	91-04	90-03	78-03	45-03	63-04	64-04	26-03	12-02	17-02	18-02	72-02
300	20-03	25-02	20-02	13-02	19-03	19-03	46-03	19-02	28-02	21-02	14-01
A	19 00	67 03	19 04	50 05	12 06	43 06	80 05	18 06	64 01	57 00	70 06
B	68-06	46-05	66-05	26-05	31-06	32-06	30-03	97-03	51-03	19-03	20-02
1	68-06	46-05	66-05	26-05	31-06	32-06	48-04	79-04	43-04	61-04	25-03
3	20-05	14-04	26-04	77-05	94-06	97-06	66-04	13-03	87-04	15-03	48-03
5	34-05	23-04	42-04	13-04	16-05	16-05	76-04	16-03	13-03	23-03	68-03
10	66-05	46-04	76-04	26-04	31-05	32-05	93-04	22-03	21-03	40-03	11-02
20	13-04	93-04	13-03	51-04	63-05	64-05	11-03	31-03	37-03	67-03	18-02
30	19-04	14-03	18-03	76-04	94-05	97-05	13-03	39-03	51-03	87-03	23-02
100	55-04	46-03	47-03	24-03	31-04	32-04	20-03	78-03	12-02	16-02	50-02
300	14-03	14-02	12-02	67-03	94-04	97-04	34-03	15-02	22-02	20-02	96-02

T = 12000 K

P = 0,1 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	74-05	53-04	85-04	30-04	43-05	50-05	11-03	26-03	26-03	43-03	12-02
3	21-04	16-03	20-03	92-04	13-04	15-04	17-03	50-03	60-03	90-03	27-02
5	32-04	26-03	31-03	15-03	22-04	25-04	22-03	70-03	83-03	12-02	37-02
10	59-04	52-03	54-03	28-03	43-04	50-04	30-03	11-02	13-02	16-02	57-02
20	10-03	10-02	95-03	54-03	88-04	10-03	43-03	15-02	19-02	19-02	85-02
30	14-03	15-02	13-02	79-03	13-03	15-03	53-03	18-02	23-02	20-02	11-01
100	29-03	45-02	36-02	25-02	43-03	50-03	10-02	33-02	35-02	21-02	22-01
300	46-03	11-01	82-02	72-02	13-02	15-02	19-02	49-02	42-02	21-02	43-01
A	34-01	11 03	31 03	80 04	17 05	56 05	89 04	18 04	10 01	98-01	91 05
B	39-05	27-04	49-04	15-04	22-05	25-05	17-02	56-02	20-02	77-03	10-01
1	39-05	27-04	48-04	15-04	22-05	25-05	98-04	20-03	15-03	27-03	82-03
3	11-04	80-04	13-03	48-04	64-05	75-05	14-03	36-03	38-03	63-03	18-02
5	18-04	13-03	19-03	78-04	11-04	12-04	17-03	48-03	53-03	88-03	25-02
10	34-04	27-03	33-03	15-03	22-04	25-04	23-03	71-03	69-03	13-02	39-02
20	63-04	53-03	57-03	29-03	43-04	50-04	32-03	11-02	14-02	17-02	60-02
30	88-04	79-03	79-03	42-03	64-04	75-04	39-03	13-02	18-02	18-02	76-02
100	22-03	25-02	21-02	13-02	22-03	25-03	73-03	26-02	31-02	21-02	15-01
300	40-03	70-02	54-02	38-02	64-03	75-03	15-02	40-02	40-02	21-02	30-01

T = 12000 K

P = 0,3 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	27-04	22-03	30-03	13-03	22-04	29-04	28-03	77-03	78-03	11-02	36-02
3	70-04	64-03	68-03	37-03	66-04	87-04	48-03	14-02	16-02	17-02	71-02
5	10-03	10-02	10-02	60-03	11-03	14-03	62-03	19-02	20-02	19-02	95-02
10	17-03	20-02	18-02	12-02	22-03	29-03	90-03	27-02	28-02	21-02	14-01
20	26-03	38-02	32-02	22-02	44-03	58-03	15-02	37-02	34-02	21-02	21-01
30	32-03	54-02	44-02	33-02	66-03	86-03	17-02	44-02	38-02	21-02	27-01
100	49-03	14-01	11-01	10-01	22-02	29-02	31-02	66-02	42-02	21-02	56-01
300	53-03	27-01	20-01	28-01	64-02	84-02	54-02	86-02	42-02	21-02	11 00
A	82-02	27 02	70 02	17 04	32 04	96 04	14 04	25 03	22 00	22-01	16 05
B	16-04	11-03	20-03	65-04	11-04	14-04	72-02	23-01	67-02	26-02	40-01
1	15-04	11-03	17-03	65-04	11-04	14-04	21-03	53-03	49-03	80-03	24-02
3	41-04	33-03	42-03	19-03	33-04	43-04	35-03	10-02	11-02	14-02	50-02
5	64-04	54-03	62-03	31-03	55-04	72-04	48-03	13-02	15-02	17-02	67-02
10	11-03	11-02	11-02	60-03	11-03	14-03	66-03	19-02	23-02	20-02	10-01
20	19-03	21-02	19-02	12-02	22-03	29-03	13-02	28-02	30-02	21-02	15-01
30	25-03	31-02	27-02	17-02	33-03	43-03	14-02	35-02	34-02	21-02	19-01
100	44-03	91-02	72-02	55-02	11-02	14-02	21-02	56-02	42-02	21-02	39-01
300	53-03	20-01	15-01	16-01	33-02	43-02	40-02	75-02	42-02	21-02	77-01

T = 12000 K

P = 1 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	90-04	87-03	10-02	58-03	13-03	18-03	81-03	21-02	20-02	18-02	96-02
3	20-03	25-02	24-02	16-02	39-03	55-03	16-02	37-02	31-02	21-02	18-01
5	27-03	39-02	36-02	26-02	65-03	91-03	19-02	46-02	36-02	21-02	24-01
10	38-03	70-02	61-02	50-02	13-02	18-02	27-02	60-02	40-02	21-02	36-01
20	47-03	12-01	10-01	97-02	26-02	36-02	39-02	73-02	42-02	21-02	56-01
30	51-03	16-01	13-01	14-01	38-02	54-02	46-02	80-02	42-02	21-02	72-01
100	53-03	32-01	25-01	40-01	12-01	17-01	87-02	11-01	42-02	21-02	15 00
300	53-03	45-01	38-01	94-01	33-01	47-01	16-01	15-01	42-02	21-02	30 00
A	20-02	62 01	15 02	34 03	54 03	15 04	21 03	37 02	49-01	52-02	26 04
B	67-04	45-03	81-03	29-03	68-04	92-04	29-01	94-01	24-01	98-02	16 00
1	55-04	45-03	59-03	29-03	68-04	92-04	60-03	15-02	15-02	16-02	67-02
3	13-03	13-02	14-02	63-03	20-03	27-03	13-02	28-02	26-02	20-02	13-01
5	20-03	22-02	22-02	14-02	34-03	46-03	15-02	36-02	31-02	21-02	17-01
10	30-03	42-02	38-02	26-02	68-03	92-03	19-02	49-02	37-02	21-02	25-01
20	42-03	77-02	66-02	51-02	14-02	18-02	32-02	64-02	41-02	21-02	39-01
30	47-03	11-01	90-02	76-02	20-02	27-02	36-02	70-02	42-02	21-02	50-01
100	53-03	25-01	19-01	24-01	67-02	90-02	62-02	95-02	42-02	21-02	10 00
300	53-03	40-01	31-01	62-01	19-01	26-01	12-01	13-01	42-02	21-02	21 00

T = 12000 K

P = 3 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	21-03	28-02	30-02	21-02	65-03	96-03	20-02	47-02	33-02	21-02	22-01
3	38-03	72-02	88-02	80-02	20-02	29-02	38-02	71-02	41-02	21-02	42-01
5	48-03	11-01	97-02	97-02	32-02	48-02	46-02	81-02	42-02	21-02	58-01
10	62-03	18-01	15-01	18-01	64-02	94-02	85-02	97-02	42-02	21-02	90-01
20	54-03	28-01	23-01	34-01	12-01	18-01	93-02	12-01	42-02	21-02	14 00
30	53-03	32-01	28-01	47-01	18-01	27-01	12-01	13-01	42-02	21-02	18 00
100	53-03	47-01	42-01	12 00	50-01	76-01	24-01	18-01	42-02	21-02	38 00
300	53-03	62-01	48-01	21 00	11 00	17 00	39-01	22-01	42-02	21-02	65 00

A	57-03	17 01	37 01	76 02	10 03	29 03	38 02	64 01	13-01	15-02	52 03
B	23-03	15-02	27-02	11-02	35-03	49-03	97-01	31 00	77-01	31-01	5 00

1	18-03	18-02	18-02	11-02	35-03	49-03	18-02	38-02	29-02	21-02	18-01
3	31-03	42-02	43-02	32-02	10-02	15-02	31-02	80-02	36-02	21-02	30-01
5	39-03	87-02	84-02	51-02	17-02	24-02	38-02	70-02	41-02	21-02	40-01
10	48-03	12-01	11-01	10-01	34-02	48-02	48-02	84-02	42-02	21-02	61-01
20	53-03	20-01	17-01	19-01	68-02	96-02	68-02	10-01	42-02	21-02	96-01
30	53-03	25-01	21-01	26-01	10-01	14-01	88-02	11-01	42-02	21-02	12 00
100	53-03	42-01	35-01	79-01	32-01	45-01	18-01	16-01	42-02	21-02	27 00
300	53-03	51-01	45-01	17 00	80-01	12 00	32-01	21-01	42-02	21-02	52 00

T = 12000 K

P = 10 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	42-03	85-02	90-02	92-02	38-02	57-02	53-02	88-02	42-02	21-02	57-01
3	62-03	19-01	19-01	26-01	11-01	16-01	96-02	12-01	42-02	21-02	12 00
5	63-03	26-01	24-01	39-01	18-01	26-01	13-01	14-01	42-02	21-02	17 00
10	63-03	36-01	33-01	89-01	33-01	49-01	19-01	18-01	42-02	21-02	26 00
20	63-03	44-01	41-01	11 00	56-01	87-01	27-01	19-01	42-02	21-02	40 00
30	63-03	48-01	45-01	15 00	78-01	12 00	33-01	21-01	42-02	21-02	50 00
100	63-03	53-01	48-01	25 00	15 00	24 00	49-01	24-01	42-02	21-02	83 00
300	63-03	53-01	48-01	29 00	20 00	32 00	64-01	24-01	42-02	21-02	10 01

A	15-03	42 00	79 00	14 02	17 02	48 02	55 01	90 00	32-02	38-03	88 02
B	88-03	56-02	98-02	51-02	21-02	30-02	35 00	11 01	26 00	10 00	18 01

1	35-03	51-02	58-02	48-02	21-02	30-02	41-02	76-02	40-02	21-02	39-01
3	50-03	13-01	13-01	14-01	62-02	88-02	70-02	10-01	42-02	21-02	79-01
5	52-03	19-01	18-01	22-01	10-01	14-01	94-02	12-01	42-02	21-02	11 00
10	53-03	29-01	26-01	42-01	20-01	28-01	14-01	14-01	42-02	21-02	18 00
20	53-03	39-01	34-01	77-01	38-01	54-01	21-01	17-01	42-02	21-02	29 00
30	53-03	44-01	39-01	10 00	54-01	78-01	26-01	19-01	42-02	21-02	37 00
100	53-03	52-01	46-01	22 00	13 00	19 00	45-01	23-01	42-02	21-02	71 00
300	53-03	53-01	48-01	28 00	19 00	30 00	54-01	24-01	42-02	21-02	96 00

T = 12000 K

P = 30 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	53-03	20-01	22-01	36-01	18-01	28-01	14-01	14-01	42-02	21-02	16 00
3	53-03	36-01	37-01	88-01	48-01	73-01	25-01	19-01	42-02	21-02	33 00
5	53-03	43-01	42-01	12 00	70-01	11 00	32-01	21-01	42-02	21-02	45 00
10	53-03	50-01	47-01	18 00	11 00	17 00	43-01	23-01	42-02	21-02	64 00
20	53-03	62-01	48-01	24 00	18 00	25 00	51-01	24-01	42-02	21-02	83 00
30	53-03	53-01	48-01	17 00	18 00	29 00	53-01	24-01	42-02	21-02	92 00
100	53-03	53-01	48-01	29 00	20 00	33 00	54-01	24-01	42-02	21-02	10 01
300	53-03	53-01	48-01	29 00	20 00	33 00	54-01	24-01	42-02	21-02	10 01

A	44-04	11 00	18 00	31 01	32 01	89 01	91 00	14 00	88-03	11-03	16 02
B	30-02	18-01	31-01	21-01	11-01	16-01	11 01	34 01	80 00	33 00	57 01

1	51-03	14-01	15-01	20-01	11-01	16-01	10-01	13-01	42-02	21-02	11 00
3	53-03	29-01	28-01	54-01	30-01	45-01	20-01	17-01	42-02	21-02	23 00
5	53-03	37-01	35-01	84-01	48-01	71-01	28-01	19-01	42-02	21-02	33 00
10	53-03	46-01	42-01	14 00	84-01	13 00	37-01	22-01	42-02	21-02	51 00
20	53-03	51-01	48-01	21 00	13 00	20 00	47-01	23-01	42-02	21-02	72 00
30	53-03	52-01	47-01	24 00	16 00	25 00	51-01	24-01	42-02	21-02	84 00
100	53-03	53-01	48-01	29 00	20 00	32 00	54-01	24-01	42-02	21-02	99 00
300	53-03	53-01	48-01	29 00	20 00	33 00	54-01	24-01	42-02	21-02	10 01

T = 12000 K

P = 100 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	53-03	41-01	42-01	12 00	81-01	13 00	38-01	22-01	42-02	21-02	49 00
3	53-03	51-01	47-01	23 00	15 00	24 00	51-01	24-01	42-02	21-02	80 00
5	53-03	53-01	48-01	27 00	18 00	29 00	54-01	24-01	42-02	21-02	92 00
10	53-03	53-01	48-01	29 00	20 00	33 00	54-01	24-01	42-02	21-02	10 01
20	53-03	53-01	48-01	29 00	20 00	33 00	54-01	24-01	42-02	21-02	10 01
30	53-03	53-01	48-01	29 00	20 00	33 00	54-01	24-01	42-02	21-02	10 01
100	53-03	53-01	48-01	29 00	20 00	33 00	54-01	24-01	42-02	21-02	10 01
300	53-03	53-01	48-01	29 00	20 00	33 00	54-01	24-01	42-02	21-02	10 01
A	11-04	26-01	33-01	58 00	51 00	13 01	12 00	19-01	19-03	27-04	28 01
B	12-01	70-01	11 00	11 00	69-01	11 00	36 01	12 02	27 01	12 01	20 02
1	53-03	34-01	35-01	86-01	58-01	91-01	33-01	21-01	42-02	21-02	36 00
3	53-03	48-01	44-01	19 00	13 00	20 00	49-01	23-01	42-02	21-02	69 00
5	53-03	52-01	47-01	24 00	16 00	26 00	53-01	24-01	42-02	21-02	84 00
10	53-03	53-01	48-01	28 00	19 00	31 00	54-01	24-01	42-02	21-02	97 00
20	53-03	53-01	48-01	29 00	20 00	33 00	54-01	24-01	42-02	21-02	10 01
30	53-03	53-01	48-01	29 00	20 00	33 00	54-01	24-01	42-02	21-02	10 01
100	53-03	53-01	48-01	29 00	20 00	33 00	54-01	24-01	42-02	21-02	10 01
300	53-03	53-01	48-01	29 00	20 00	33 00	54-01	24-01	42-02	21-02	10 01