

T = 20000 K

P = 0,001 ATM

	1	2	3	4	5	6	7	8	9	10	Сумма
1	18-09	65-09	35-09	19-07	61-08	25-08	30-08	97-08	31-04	80-04	11-03
3	53-09	20-08	11-08	58-07	18-07	74-08	92-08	29-07	53-04	15-03	20-03
5	88-09	33-08	18-08	96-07	31-07	12-07	15-07	48-07	62-04	20-03	28-03
10	18-08	65-08	35-08	19-06	61-07	25-07	30-07	97-07	76-04	21-03	28-03
20	35-08	13-07	71-08	38-06	12-06	50-07	81-07	19-06	65-04	25-03	34-03
30	53-08	20-07	11-07	58-06	18-06	74-07	92-07	29-06	91-04	27-03	36-03
100	18-07	65-07	35-07	19-05	61-06	25-06	30-06	97-06	11-03	31-03	42-03
300	53-07	20-06	11-06	58-05	18-05	74-06	92-06	29-05	12-03	34-03	48-03
A	77 02	32 06	85 08	22 08	48 08	22 09	76 08	59 08	16 08	53 07	44 09
B	88-10	33-09	18-09	96-08	31-08	12-08	15-08	48-08	28-04	77-04	10-03
1	88-10	33-09	18-09	96-08	31-08	12-08	15-08	48-08	21-04	54-04	76-04
3	26-09	98-09	53-09	29-07	92-08	37-08	46-08	14-07	43-04	11-03	15-03
5	44-09	16-08	88-09	48-07	15-07	62-08	76-08	24-07	54-04	14-03	20-03
10	88-09	33-08	18-08	96-07	31-07	12-07	15-07	48-07	69-04	16-03	25-03
20	18-08	65-08	35-08	19-06	61-07	25-07	30-07	97-07	81-04	23-03	31-03
30	26-08	98-08	53-08	29-06	92-07	37-07	46-07	14-06	87-04	25-03	34-03
100	88-08	33-07	18-07	96-06	31-06	12-06	15-06	48-06	10-03	30-03	40-03
300	26-07	98-07	53-07	29-05	92-06	37-06	46-06	14-05	12-03	34-03	46-03

T = 20000 K

P = 0,01 ATM

	1	2	3	4	5	6	7	8	9	10	Сумма
1	12-07	47-07	37-07	46-06	14-06	62-07	50-06	17-05	88-04	18-03	27-03
3	35-07	14-06	11-06	14-05	43-06	19-06	15-05	52-05	10-03	23-03	34-03
5	58-07	23-06	18-06	23-05	72-06	31-06	25-05	83-05	11-03	26-03	39-03
10	12-06	47-06	37-06	46-05	14-05	62-06	50-05	16-04	12-03	30-03	45-03
20	23-06	94-06	74-06	92-05	29-05	12-05	92-05	29-04	13-03	33-03	52-03
30	34-06	14-05	11-05	14-04	43-05	19-05	13-04	40-04	14-03	36-03	58-03
100	11-05	47-05	37-05	46-04	14-04	62-05	55-04	10-03	18-03	46-03	86-03
300	31-05	14-04	11-04	14-03	43-04	19-04	72-04	19-03	27-03	68-03	14-02
A	12 01	54 04	16 05	53 06	14 07	74 07	29 07	22 07	87 05	28 05	14 08
B	58-08	23-07	18-07	23-06	72-07	31-07	25-06	87-06	65-03	76-03	14-02
1	58-08	23-07	18-07	23-06	72-07	31-07	25-06	86-06	84-04	14-03	23-03
3	17-07	70-07	55-07	69-06	22-06	93-07	76-06	26-05	10-03	20-03	31-03
5	29-07	12-06	92-07	11-05	38-06	16-06	12-05	43-05	11-03	24-03	35-03
10	58-07	23-06	18-06	23-05	72-06	31-06	25-05	84-05	12-03	28-03	41-03
20	12-06	47-06	37-06	46-05	14-05	62-06	49-05	16-04	13-03	31-03	47-03
30	17-06	70-06	55-06	69-05	22-05	93-06	73-05	24-04	13-03	33-03	51-03
100	57-06	23-05	18-05	23-04	72-05	31-05	22-04	65-04	16-03	41-03	70-03
300	17-05	70-05	55-05	69-04	22-04	93-05	51-04	14-03	22-03	54-03	11-02

T = 20000 K

P = 0,03 ATM

	1	2	3	4	5	6	7	8	9	10	Сумма
1	93-07	39-06	33-06	17-05	51-06	25-06	48-05	14-04	11-03	22-03	35-03
3	28-06	12-05	99-06	50-05	15-05	75-06	14-04	38-04	13-03	26-03	47-03
5	46-06	19-05	16-05	84-05	25-05	12-05	17-04	57-04	14-03	32-03	56-03
10	90-06	39-05	33-05	17-04	51-05	25-05	32-04	93-04	17-03	40-03	72-03
20	17-05	78-05	86-05	33-04	10-04	50-05	52-04	15-03	22-03	50-03	99-03
30	25-05	12-04	99-05	50-04	15-04	75-05	61-04	20-03	25-03	59-03	12-02
100	75-05	39-04	30-04	17-03	51-04	25-04	12-03	34-03	43-03	11-02	23-02
300	18-04	11-03	78-04	48-03	15-03	75-04	17-03	63-03	80-03	24-02	49-02
A	15 00	68 03	21 04	81 05	25 06	15 07	70 06	49 06	11 05	36 04	30 07
B	46-07	19-06	17-06	84-06	25-06	12-06	24-05	84-05	22-02	22-02	44-02
1	46-07	19-06	16-06	84-06	25-06	12-06	24-05	83-05	10-03	18-03	29-03
3	14-06	58-06	50-06	25-05	76-06	37-06	72-05	23-04	12-03	24-03	40-03
5	23-06	97-06	83-06	42-05	13-05	62-06	12-04	38-04	13-03	28-03	47-03
10	46-06	19-05	16-05	84-05	25-05	12-05	21-04	64-04	15-03	34-03	59-03
20	91-06	39-05	33-05	17-04	51-05	25-05	37-04	10-03	19-03	41-03	77-03
30	14-05	58-05	50-05	25-04	76-05	37-05	50-04	14-03	21-03	47-03	92-03
100	42-05	19-04	16-04	84-04	25-04	12-04	97-04	28-03	34-03	80-03	17-02
300	11-04	58-04	46-04	25-03	76-04	37-04	15-03	58-03	58-03	16-02	33-02

T = 20000 K

P = 0,1 ATM

	1	2	3	4	5	6	7	8	9	10	Сумма
1	94-06	41-05	38-05	74-05	21-05	13-05	38-04	10-03	16-03	33-03	65-03
3	26-05	12-04	11-04	22-04	62-05	40-05	68-04	21-03	25-03	56-03	12-02
5	42-05	20-04	18-04	37-04	10-04	67-05	85-04	30-03	32-03	77-03	16-02
10	78-05	41-04	36-04	74-04	21-04	13-04	12-03	41-03	47-03	12-02	24-02
20	14-04	81-04	66-04	15-03	42-04	27-04	16-03	59-03	71-03	20-02	38-02
30	19-04	12-03	92-04	22-03	62-04	40-04	19-03	73-03	91-03	27-02	51-02
100	45-04	39-03	26-03	71-03	20-03	13-03	31-03	14-02	22-02	71-02	13-01
300	81-04	11-02	67-03	20-02	59-03	40-03	52-03	27-02	53-02	16-01	30-01
A	14-01	65 02	20 03	86 04	30 05	22 06	12 06	78 05	88 03	30 03	46 06
B	49-06	20-05	18-05	37-05	10-05	67-06	27-04	94-04	76-02	75-02	15-01
1	48-06	20-05	18-05	37-05	10-05	67-06	26-04	75-04	15-03	25-03	51-03
3	14-05	62-05	55-05	11-04	31-05	20-05	61-04	16-03	21-03	41-03	68-03
5	23-05	10-04	91-05	18-04	52-05	34-05	84-04	22-03	26-03	54-03	12-02
10	44-05	20-04	18-04	37-04	10-04	67-05	12-03	34-03	36-03	81-03	17-02
20	82-05	41-04	36-04	74-04	21-04	13-04	16-03	50-03	51-03	13-02	26-02
30	12-04	62-04	52-04	11-03	31-04	20-04	18-03	62-03	65-03	17-02	34-02
100	31-04	20-03	15-03	37-03	10-03	67-04	28-03	11-02	14-02	42-02	60-02
300	64-04	59-03	39-03	11-02	31-03	20-03	43-03	20-02	31-02	10-01	16-01

T = 20000 K

P = 0,3 ATM

	1	2	3	4	5	6	7	8	9	10	Сумма
1	69-05	36-04	32-04	36-04	89-05	81-05	14-03	51-03	44-03	11-02	23-02
3	17-04	11-03	92-04	11-03	27-04	24-04	23-03	87-03	93-03	25-02	49-02
5	25-04	18-03	15-03	18-03	45-04	40-04	29-03	12-02	14-02	39-02	74-02
10	41-04	34-03	29-03	35-03	89-04	81-04	40-03	18-02	24-02	68-02	13-01
20	62-04	86-03	50-03	70-03	18-03	16-03	56-03	27-02	39-02	12-01	21-01
30	76-04	95-03	71-03	10-02	26-03	24-03	70-03	35-02	52-02	16-01	29-01
100	11-03	26-02	19-02	33-02	86-03	81-03	14-02	77-02	12-01	34-01	64-01
300	12-03	57-02	40-02	86-02	24-02	24-02	26-02	14-01	23-01	52-01	12 00
A	16-02	73 01	22 02	10 04	38 04	31 05	18 05	10 05	89 02	32 02	64 05
B	42-05	18-04	16-04	18-04	45-05	40-05	24-03	84-03	23-01	23-01	47-01
1	39-05	18-04	18-04	18-04	45-05	40-05	13-03	36-03	34-03	07-02	16-02
3	10-04	54-04	49-04	54-04	13-04	12-04	22-03	70-03	63-03	15-02	32-02
5	16-04	89-04	76-04	89-04	22-04	20-04	26-03	93-03	86-03	22-02	46-02
10	28-04	18-03	14-03	18-03	45-04	40-04	35-03	13-02	14-02	39-02	76-02
20	48-04	35-03	28-03	36-03	89-04	81-04	45-03	19-02	23-02	70-02	13-01
30	59-04	52-03	37-03	53-03	13-03	12-03	54-03	24-02	31-02	96-02	17-01
100	10-03	16-02	10-02	17-02	44-03	40-03	96-03	49-02	80-02	25-01	44-01
300	12-03	40-02	26-02	49-02	13-02	12-02	18-02	94-02	17-01	45-01	67-01

T = 20000 K

P = 1 ATM

	1	2	3	4	5	6	7	8	9	10	Сумма
1	42-04	36-03	32-03	26-03	58-04	72-04	68-03	36-02	27-02	75-02	16-01
3	77-04	99-03	91-03	76-03	18-03	21-03	12-02	58-02	64-02	17-01	34-01
5	95-04	15-02	14-02	13-02	29-03	36-03	15-02	76-02	87-02	24-01	47-01
10	11-03	27-02	23-02	25-02	58-03	71-03	23-02	11-01	14-01	36-01	72-01
20	12-03	45-02	36-02	50-02	11-02	14-02	34-02	16-01	20-01	46-01	10 00
30	12-03	58-02	46-02	71-02	17-02	21-02	49-02	20-01	25-01	54-01	12 00
100	12-03	10-01	89-02	19-01	53-02	70-02	85-02	35-01	40-01	61-01	20 00
300	12-03	13-01	13-01	43-01	14-01	20-01	15-01	51-01	47-01	61-01	26 00
A	15-03	66 00	19 01	95 02	37 03	32 04	16 04	79 03	72 01	28 01	61 04
B	44-04	19-03	17-03	13-03	29-04	36-04	26-02	89-02	79-01	78-01	17 00
1	29-04	18-03	16-03	13-03	29-04	36-04	51-03	18-02	18-02	42-02	87-02
3	61-04	54-03	43-03	39-03	88-04	11-03	89-03	36-02	36-02	11-01	20-01
5	80-04	88-03	68-03	66-03	15-03	18-03	12-02	49-02	54-02	16-01	30-01
10	10-03	17-02	12-02	13-02	29-03	36-03	17-02	78-02	92-02	27-01	50-01
20	12-03	30-02	22-02	25-02	58-03	72-03	24-02	11-01	15-01	40-01	77-01
30	12-03	41-02	30-02	38-02	87-03	11-02	40-02	14-01	19-01	47-01	98-01
100	12-03	87-02	67-02	12-01	28-02	36-02	60-02	28-01	35-01	60-01	16 00
300	12-03	12-01	11-01	30-01	81-02	10-01	11-01	44-01	45-01	61-01	23 00

T = 20000 K

P = 3 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	11-03	23-02	23-02	18-02	38-03	55-03	37-02	13-01	12-01	32-01	69-01
3	12-03	51-02	44-02	51-02	11-02	16-02	58-02	25-01	24-01	51-01	12 00
5	12-03	70-02	60-02	83-02	19-02	27-02	75-02	31-01	30-01	58-01	15 00
10	12-03	97-02	87-02	15-01	37-02	54-02	10-01	39-01	39-01	61-01	19 00
20	12-03	12-01	12-01	26-01	71-02	11-01	14-01	50-01	45-01	61-01	24 00
30	12-03	13-01	13-01	35-01	10-01	16-01	17-01	56-01	47-01	61-01	27 00
100	12-03	14-01	14-01	71-01	28-01	48-01	35-01	76-01	48-01	61-01	40 00
300	12-03	14-01	14-01	10 00	60-01	12 00	64-01	95-01	48-01	61-01	58 00
A	19-04	76-01	20 00	11 02	47 02	40 03	17 03	69 02	78 00	33 00	70 03
B	35-03	15-02	13-02	91-03	19-03	28-03	21-01	72-01	24 00	25 00	59 00
1	96-04	14-02	11-02	90-03	19-03	28-03	25-02	93-02	83-02	24-01	48-01
3	12-03	35-02	28-02	26-02	58-03	83-03	47-02	18-01	18-01	44-01	95-01
5	12-03	51-02	40-02	43-02	96-03	14-02	56-02	24-01	24-01	52-01	12 00
10	12-03	78-02	63-02	84-02	19-02	28-02	82-02	32-01	34-01	59-01	16 00
20	12-03	11-01	90-02	16-01	38-02	55-02	10-01	42-01	42-01	61-01	20 00
30	12-03	12-01	11-01	22-01	56-02	82-02	12-01	48-01	45-01	61-01	22 00
100	12-03	14-01	14-01	55-01	17-01	26-01	25-01	68-01	48-01	61-01	33 00
300	12-03	14-01	14-01	92-01	43-01	74-01	48-01	85-01	48-01	61-01	48 00

T = 20000 K

P = 10 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	12-03	92-02	88-02	12-01	29-02	47-02	13-01	48-01	40-01	61-01	20 00
3	12-03	13-01	12-01	29-01	82-02	14-01	23-01	88-01	47-01	61-01	28 00
5	12-03	14-01	13-01	42-01	13-01	22-01	30-01	75-01	48-01	61-01	32 00
10	12-03	14-01	14-01	64-01	24-01	42-01	43-01	85-01	48-01	61-01	40 00
20	12-03	14-01	14-01	87-01	40-01	75-01	61-01	97-01	48-01	61-01	50 00
30	12-03	14-01	14-01	98-01	52-01	10 00	74-01	10 00	48-01	61-01	57 00
100	12-03	14-01	14-01	11 00	96-01	23 00	12 00	12 00	48-01	61-01	81 00
300	12-03	14-01	14-01	11 00	11 00	34 00	14 00	13 00	48-01	61-01	97 00
A	23-05	78-02	18-01	13 01	56 01	47 02	15 02	43 01	71-01	34-01	73 02
B	30-02	12-01	11-01	71-02	15-02	24-02	18 00	63 00	87 00	95 00	27 01
1	12-03	73-02	64-02	67-02	15-02	24-02	10-01	40-01	35-01	59-01	17 00
3	12-03	12-01	10-01	18-01	44-02	70-02	17-01	59-01	45-01	61-01	24 00
5	12-03	13-01	12-01	28-01	72-02	12-01	22-01	67-01	47-01	61-01	27 00
10	12-03	14-01	14-01	48-01	14-01	23-01	32-01	77-01	48-01	61-01	33 00
20	12-03	14-01	14-01	72-01	26-01	44-01	46-01	88-01	48-01	61-01	41 00
30	12-03	14-01	14-01	86-01	36-01	64-01	57-01	96-01	48-01	61-01	48 00
100	12-03	14-01	14-01	11 00	81-01	17 00	10 00	12 00	48-01	61-01	72 00
300	12-03	14-01	14-01	11 00	11 00	30 00	14 00	12 00	48-01	61-01	93 00

T = 20000 K

P = 30 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	12-03	14-01	14-01	48-01	19-01	41-01	46-01	87-01	48-01	61-01	38 00
3	12-03	14-01	14-01	85-01	44-01	10 00	76-01	11 00	48-01	61-01	55 00
5	12-03	14-01	14-01	10 00	62-01	15 00	93-01	11 00	48-01	61-01	65 00
10	12-03	14-01	14-01	11 00	88-01	22 00	12 00	12 00	48-01	61-01	80 00
20	12-03	14-01	14-01	11 00	11 00	30 00	14 00	13 00	48-01	61-01	92 00
30	12-03	14-01	14-01	11 00	11 00	34 00	14 00	13 00	48-01	61-01	97 00
100	12-03	14-01	14-01	11 00	11 00	36 00	14 00	13 00	48-01	61-01	99 00
300	12-03	14-01	14-01	11 00	11 00	36 00	14 00	13 00	48-01	61-01	99 00
A	40-06	12-02	25-02	19 00	70 00	48 01	14 01	41 00	10-01	57-02	76 01
B	17-01	70-01	58-01	43-01	11-01	23-01	11 01	37 01	29 01	33 01	11 02
1	12-03	13-01	13-01	33-01	11-01	23-01	35-01	79-01	48-01	61-01	32 00
3	12-03	14-01	14-01	70-01	29-01	63-01	61-01	98-01	48-01	61-01	46 00
5	12-03	14-01	14-01	88-01	45-01	99-01	77-01	11 00	48-01	61-01	55 00
10	12-03	14-01	14-01	10 00	71-01	17 00	10 00	12 00	48-01	61-01	70 00
20	12-03	14-01	14-01	11 00	97-01	26 00	12 00	12 00	48-01	61-01	85 00
30	12-03	14-01	14-01	11 00	11 00	30 00	13 00	12 00	48-01	61-01	92 00
100	12-03	14-01	14-01	11 00	11 00	36 00	14 00	13 00	48-01	61-01	99 00
300	12-03	14-01	14-01	11 00	11 00	36 00	14 00	13 00	48-01	61-01	99 00

T = 20000 K

P = 100 ATM

	1	2	3	4	5	6	7	8	9	10	Сумма
1	12-03	14-01	14-01	10 00	78-01	21 00	12 00	12 00	48-01	61-01	78 00
3	12-03	14-01	14-01	11 00	11 00	33 00	14 00	13 00	48-01	61-01	96 00
5	12-03	14-01	14-01	11 00	11 00	36 00	14 00	13 00	48-01	61-01	99 00
10	12-03	14-01	14-01	11 00	11 00	36 00	14 00	13 00	48-01	61-01	99 00
20	12-03	14-01	14-01	11 00	11 00	36 00	14 00	13 00	48-01	61-01	99 00
30	12-03	14-01	14-01	11 00	11 00	36 00	14 00	13 00	48-01	61-01	99 00
100	12-03	14-01	14-01	11 00	11 00	36 00	14 00	13 00	48-01	61-01	99 00
300	12-03	14-01	14-01	11 00	11 00	36 00	14 00	13 00	48-01	61-01	99 00
A	74-07	22-03	41-03	32-01	90-01	53 00	13 00	32-01	14-02	94-03	82 00
B	92-01	37 00	26 00	24 00	87-01	22 00	53 01	18 02	98 01	14 02	46 02
1	12-03	14-01	14-01	94-01	60-01	16 00	10 00	12 00	48-01	61-01	67 00
3	12-03	14-01	14-01	11 00	10 00	29 00	14 00	12 00	48-01	61-01	90 00
5	12-03	14-01	14-01	11 00	11 00	34 00	14 00	13 00	48-01	61-01	96 00
10	12-03	14-01	14-01	11 00	11 00	36 00	14 00	13 00	48-01	61-01	99 00
20	12-03	14-01	14-01	11 00	11 00	36 00	14 00	13 00	48-01	61-01	99 00
30	12-03	14-01	14-01	11 00	11 00	36 00	14 00	13 00	48-01	61-01	99 00
100	12-03	14-01	14-01	11 00	11 00	36 00	14 00	13 00	48-01	61-01	99 00
300	12-03	14-01	14-01	11 00	11 00	36 00	14 00	13 00	48-01	61-01	99 00