

T = 9000 K

P = 0,001 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	38-08	37-07	12-06	22-07	18-08	99-09	33-05	27-05	96-06	44-06	76-05
3	11-07	11-06	35-06	65-07	55-08	30-08	58-05	44-05	15-05	96-06	13-04
5	19-07	19-06	58-06	11-06	91-08	50-08	72-05	54-05	19-05	14-05	17-04
10	36-07	37-06	12-05	22-06	18-07	10-07	92-05	89-05	26-05	24-05	23-04
20	76-07	75-06	23-05	43-06	37-07	20-07	11-04	87-05	38-05	40-05	31-04
30	11-06	11-05	35-06	65-06	56-07	30-07	11-04	10-04	48-05	56-05	37-04
100	36-06	37-05	11-04	22-05	19-06	10-06	14-04	14-04	11-04	14-04	70-04
300	11-05	11-04	30-04	65-05	56-06	30-06	16-04	21-04	24-04	29-04	14-03
A	37 03	10 07	27 07	41 08	48 08	12 09	12 08	21 07	21 02	72 00	23 09
B	18-08	19-07	58-07	11-07	10-08	51-09	34-05	12-04	27-05	43-06	18-04
1	19-08	19-07	58-07	11-07	10-08	51-09	23-05	21-05	81-06	29-06	56-05
3	57-08	56-07	18-06	33-07	31-08	15-08	45-05	35-05	12-05	62-06	10-04
5	95-08	93-07	29-06	54-07	52-08	25-08	58-05	44-05	15-05	88-06	13-04
10	19-07	19-06	58-06	11-06	10-07	51-08	79-05	58-05	20-05	14-05	18-04
20	38-07	37-06	12-05	22-06	21-07	10-07	99-05	75-05	28-05	24-05	24-04
30	57-07	56-06	19-05	33-06	31-07	15-07	11-04	86-05	34-05	33-05	29-04
100	19-06	19-05	57-05	11-05	10-06	51-07	13-04	13-04	68-05	88-05	50-04
300	57-06	56-05	16-04	33-05	31-06	15-06	15-04	18-04	15-04	20-04	94-04

T = 9000 K

P = 0,01 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	49-07	48-06	15-05	30-06	56-07	25-07	96-05	77-05	30-05	30-05	26-04
3	15-06	14-05	45-05	90-06	17-06	74-07	12-04	11-04	60-05	72-05	43-04
5	24-06	24-05	75-05	15-05	28-06	12-06	13-04	13-04	86-05	11-04	58-04
10	49-06	48-05	14-04	30-05	56-06	25-06	14-04	17-04	15-04	18-04	67-04
20	98-06	96-05	26-04	60-05	11-05	50-06	16-04	24-04	24-04	28-04	14-03
30	15-05	14-04	35-04	90-05	17-05	74-06	17-04	28-04	32-04	35-04	16-03
100	48-05	48-04	92-04	28-04	56-05	25-05	23-04	51-04	75-04	60-04	39-03
300	14-04	14-03	22-03	77-04	17-04	74-05	32-04	94-04	14-03	82-04	63-03
A	28 02	79 05	19 06	23 07	19 07	50 07	32 06	35 05	16 01	56-01	97 07
B	24-07	24-06	75-06	15-06	30-07	13-07	43-04	14-03	29-04	47-05	22-03
1	24-07	24-06	75-06	15-06	30-07	13-07	86-05	65-05	22-05	18-05	20-04
3	74-07	72-06	22-05	46-06	90-07	39-07	11-04	98-05	40-05	43-05	33-04
5	12-06	12-05	38-05	76-06	15-06	65-07	13-04	12-04	55-05	65-05	42-04
10	24-06	24-05	75-05	15-05	30-06	13-06	14-04	15-04	88-05	11-04	61-04
20	49-06	48-05	15-04	31-05	60-06	26-06	16-04	19-04	14-04	19-04	91-04
30	74-06	72-05	22-04	46-05	90-06	39-06	17-04	22-04	20-04	24-04	12-03
100	24-05	24-04	62-04	15-04	30-05	13-05	22-04	38-04	48-04	48-04	26-03
300	73-06	72-04	14-03	44-04	90-05	39-05	29-04	67-04	10-03	74-04	55-03

T = 9000 K

P = 0,03 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	18-06	18-05	54-05	12-05	30-06	13-06	13-04	12-04	78-05	86-05	50-04
3	55-06	52-05	16-04	35-05	89-06	39-06	15-04	20-04	17-04	19-04	98-04
5	91-06	88-05	24-04	59-05	15-05	84-06	17-04	25-04	25-04	27-04	14-03
10	18-05	18-04	42-04	12-04	30-05	13-05	20-04	35-04	41-04	39-04	21-03
20	36-05	35-04	77-04	24-04	60-05	26-05	24-04	51-04	67-04	54-04	34-03
30	54-05	52-04	10-03	35-04	89-05	39-05	28-04	66-04	84-04	63-04	45-03
100	17-04	17-03	25-03	10-03	30-04	13-04	44-04	12-03	16-03	85-04	10-02
300	48-04	42-03	59-03	28-03	89-04	39-04	73-04	20-03	25-03	87-04	22-02
A	78 01	21 05	48 05	51 06	37 06	93 06	47 05	46 04	41 00	15-01	19 07
B	91-07	88-06	27-05	60-06	16-06	70-07	16-03	54-03	10-03	16-04	82-03
1	91-07	88-06	27-05	60-06	16-06	70-07	12-04	11-04	48-05	52-05	38-04
3	27-06	26-05	80-05	18-05	47-06	21-06	15-04	17-04	10-04	12-04	66-04
5	46-06	44-05	13-04	30-05	79-06	35-06	17-04	20-04	15-04	18-04	92-04
10	91-06	88-05	26-04	60-05	16-05	70-06	20-04	27-04	25-04	28-04	14-03
20	18-05	18-04	48-04	12-04	32-05	14-05	24-04	38-04	42-04	42-04	23-03
30	27-05	26-04	69-04	18-04	47-05	21-05	26-04	47-04	56-04	51-04	30-03
100	90-05	88-04	17-03	58-04	16-04	70-05	38-04	89-04	12-03	78-04	68-03
300	26-04	26-03	39-03	16-03	47-04	21-04	59-04	16-03	21-03	87-04	14-02

T = 9000 K

P = 0,1 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	68-06	62-05	19-04	47-05	18-06	86-06	18-04	25-04	22-04	22-04	12-03
3	20-05	19-04	47-04	14-04	55-05	26-05	24-04	47-04	48-04	41-04	25-03
5	33-05	31-04	73-04	24-04	91-05	43-05	29-04	61-04	66-04	52-04	35-03
10	65-05	62-04	12-03	47-04	18-04	86-06	38-04	87-04	97-04	67-04	56-03
20	13-04	12-03	21-03	89-04	36-04	17-04	52-04	13-03	14-03	81-04	89-03
30	19-04	19-03	27-03	13-03	55-04	26-04	63-04	16-03	17-03	85-04	12-02
100	57-04	62-03	70-03	39-03	18-03	86-04	12-03	27-03	27-03	87-04	28-02
300	15-03	18-02	19-02	11-02	54-03	26-03	23-03	42-03	33-03	87-04	67-02
A	21 01	58 04	11 05	10 06	63 05	14 06	61 04	50 03	11 00	42-02	33 06
B	33-06	31-05	94-05	24-05	96-06	47-06	56-03	19-02	35-03	55-04	28-02
1	33-06	31-05	94-05	24-05	96-06	47-06	18-04	21-04	12-04	14-04	82-04
3	10-05	94-05	28-04	74-05	29-05	14-05	23-04	34-04	28-04	30-04	16-03
5	18-05	16-04	45-04	12-04	48-05	23-05	27-04	44-04	42-04	40-04	23-03
10	33-05	31-04	82-04	24-04	96-05	47-05	33-04	62-04	69-04	56-04	38-03
20	68-05	62-04	14-03	49-04	19-04	94-05	43-04	96-04	10-03	72-04	60-03
30	98-05	94-04	19-03	72-04	29-04	14-04	51-04	12-03	13-03	80-04	79-03
100	31-04	31-03	45-03	22-03	96-04	47-04	88-04	21-03	23-03	87-04	18-02
300	87-04	93-03	10-02	62-03	29-03	14-03	16-03	33-03	31-03	87-04	40-02

T = 9000 K

P = 0,3 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	22-05	20-04	58-04	18-04	98-05	53-05	32-04	58-04	53-04	43-04	30-03
3	64-05	59-04	13-03	53-04	29-04	16-04	51-04	11-03	98-04	67-04	62-03
5	10-04	98-04	20-03	89-04	49-04	26-04	66-04	14-03	13-03	77-04	89-03
10	20-04	20-03	33-03	17-03	98-04	53-04	96-04	20-03	18-03	86-04	14-02
20	39-04	39-03	53-03	32-03	20-03	11-03	14-03	28-03	24-03	87-04	23-02
30	56-04	58-03	73-03	46-03	29-03	16-03	18-03	34-03	27-03	87-04	32-02
100	16-03	19-02	20-02	15-02	98-03	53-03	41-03	59-03	33-03	87-04	84-02
300	36-03	53-02	49-02	43-02	29-02	16-02	80-03	93-03	33-03	87-04	22-01
A	64 00	16 04	26 04	23 05	12 05	24 05	85 03	66 02	35-01	13-02	64 06
B	11-05	39-05	29-04	94-05	51-05	29-05	17-02	57-02	11-02	17-03	87-02
1	11-05	99-05	29-04	94-05	51-05	29-05	28-04	44-04	32-04	32-04	19-03
3	32-05	30-04	81-04	28-04	15-04	88-05	42-04	81-04	70-04	56-04	41-03
5	54-05	49-04	12-03	47-04	26-04	15-04	52-04	10-03	96-04	68-04	58-03
10	11-04	99-04	21-03	94-04	51-04	29-04	72-04	14-03	15-03	81-04	94-03
20	21-04	20-03	36-03	18-03	10-03	59-04	10-03	21-03	20-03	86-04	15-02
30	31-04	30-03	48-03	27-03	15-03	88-04	13-03	25-03	23-03	87-04	20-02
100	94-04	98-03	12-02	83-03	51-03	29-03	26-03	45-03	32-03	87-04	50-02
300	24-03	29-02	29-02	24-02	15-02	88-03	55-03	73-03	33-03	87-04	12-01

T = 9000 K

P = 1 ATM

	1	2	3	4	5	6	7	8	9	10	СУММА
1	61-05	70-04	18-03	82-04	64-04	44-04	88-04	15-03	11-03	73-04	68-03
3	23-04	21-03	38-03	24-03	19-03	13-03	17-03	28-03	19-03	86-04	19-02
5	37-04	35-03	57-03	41-03	32-03	22-03	23-03	37-03	23-03	87-04	28-02
10	70-04	69-03	97-03	76-03	64-03	44-03	39-03	54-03	28-03	87-04	49-02
20	13-03	14-02	17-02	15-02	13-02	88-03	61-03	76-03	32-03	87-04	86-02
30	18-03	20-02	23-02	22-02	19-02	13-02	78-03	92-03	33-03	87-04	12-01
100	43-03	62-02	62-02	70-02	61-02	43-02	19-02	15-02	33-03	87-04	34-01
300	79-03	16-01	14-01	20-01	17-01	12-01	41-02	23-02	33-03	87-04	87-01
A	17 00	40 03	50 03	40 04	18 04	31 04	85 02	67 01	85-02	32-03	99 04
B	41-05	35-04	10-03	44-04	33-04	24-04	57-02	19-01	36-02	57-03	29-01
1	41-05	35-04	97-04	44-04	32-04	24-04	65-04	11-03	83-04	63-04	56-03
3	12-04	11-03	24-03	13-03	98-04	73-04	12-03	20-03	16-03	83-04	12-02
5	20-04	18-03	36-03	22-03	16-03	12-03	16-03	27-03	20-03	86-04	18-02
10	39-04	35-03	61-03	43-03	32-03	24-03	24-03	40-03	26-03	87-04	30-02
20	74-04	70-03	10-02	84-03	65-03	48-03	43-03	58-03	30-03	37-04	52-02
30	10-03	10-02	14-02	12-02	98-03	72-03	53-03	71-03	32-03	87-04	72-02
100	29-03	34-02	38-02	40-02	32-02	24-02	11-02	12-02	35-03	87-04	20-01
300	62-03	96-02	94-02	12-01	95-02	71-02	27-02	20-02	33-03	87-04	53-01

T = 9000 K

P = 3 ATM

	1	2	3	4	5	6	7	8	9	10	CUMMA
1	28-04	23-03	46-03	35-03	35-03	34-03	31-03	44-03	21-03	87-04	28-02
3	75-04	68-03	11-02	10-02	10-02	10-02	69-03	80-03	29-03	87-04	68-02
5	12-03	11-02	16-02	17-02	17-02	17-02	96-03	10-02	32-03	87-04	10-01
10	20-03	22-02	29-02	33-02	34-02	33-02	16-02	14-02	33-03	87-04	19-01
20	34-03	42-02	50-02	65-02	67-02	65-02	27-02	19-02	33-03	87-04	34-01
30	45-03	61-02	69-02	96-02	98-02	95-02	36-02	22-02	33-03	87-04	49-01
100	66-03	17-01	17-01	30-01	29-01	26-01	75-02	30-02	33-03	87-04	10-00
300	12-02	38-01	35-01	79-01	68-01	64-01	11-01	34-02	33-03	87-04	30-00
A	47-01	11-03	12-03	77-03	30-03	45-03	96-01	74-00	20-02	30-04	18-04
B	15-04	12-03	31-03	20-03	18-03	18-03	17-01	56-01	10-01	16-02	86-01
1	14-04	12-03	27-03	20-03	18-03	18-03	20-03	30-03	19-03	85-04	17-02
3	42-04	35-03	66-03	59-03	53-03	54-03	47-03	60-03	28-03	87-04	41-02
5	67-04	58-03	10-02	97-03	89-03	89-03	62-03	78-03	31-03	87-04	62-02
10	12-03	11-02	18-02	19-02	18-02	18-02	99-03	11-02	33-03	87-04	11-01
20	22-03	23-02	31-02	38-02	35-02	35-02	16-02	15-02	33-03	87-04	20-01
30	30-03	34-02	43-02	56-02	52-02	52-02	24-02	18-02	33-03	87-04	29-01
100	69-03	10-01	11-01	18-01	17-01	17-01	56-02	28-02	33-03	87-04	83-01
300	11-02	27-01	26-01	51-01	45-01	44-01	10-01	34-02	33-03	87-04	21-00

T = 9000 K

P = 10 ATM

	1	2	3	4	5	6	7	8	9	10	CUMMA
1	11-03	87-03	15-02	19-02	22-02	32-02	15-02	13-02	31-03	87-04	13-01
3	26-03	25-02	37-02	56-02	63-02	91-02	35-02	21-02	33-03	87-04	34-01
5	37-03	41-02	56-02	90-02	10-01	14-01	49-02	25-02	33-03	87-04	52-01
10	58-03	78-02	97-02	17-01	19-01	26-01	74-02	30-02	33-03	87-04	92-01
20	82-03	14-01	16-01	33-01	35-01	46-01	10-01	32-02	33-03	87-04	16-00
30	97-03	20-01	22-01	48-01	48-01	61-01	11-01	34-02	33-03	87-04	21-00
100	12-02	46-01	47-01	13-00	11-00	12-00	14-01	35-02	33-03	87-04	47-00
300	12-02	78-01	72-01	26-00	16-00	17-00	14-01	35-02	33-03	87-04	76-00
A	10-01	21-02	20-02	15-03	82-02	76-02	86-00	75-01	34-03	15-04	35-03
B	69-04	45-03	11-02	11-02	11-02	16-02	51-01	17-00	32-01	65-02	27-00
1	62-04	45-03	91-03	11-02	11-02	16-02	95-03	10-02	31-03	87-04	76-02
3	16-03	14-02	23-02	32-02	33-02	48-02	24-02	17-02	33-03	87-04	20-01
5	25-03	22-02	35-02	53-02	54-02	80-02	34-02	21-02	33-03	87-04	30-01
10	42-03	44-02	62-02	10-01	11-01	15-01	55-02	27-02	33-03	87-04	56-01
20	65-03	65-02	11-01	20-01	21-01	29-01	85-02	32-02	33-03	87-04	10-00
30	81-03	12-01	15-01	30-01	30-01	40-01	10-01	34-02	33-03	87-04	14-00
100	12-02	34-01	35-01	90-01	81-01	95-01	14-01	35-02	33-03	87-04	35-00
300	12-02	86-01	61-01	21-00	15-00	16-00	14-01	35-02	33-03	87-04	66-00

T = 9000 K

P = 30 ATM

	1	2	3	4	5	6	7	8	9	10	CUMMA
1	37-03	32-02	48-02	86-02	10-01	20-01	61-02	27-02	33-03	87-04	56-01
3	71-03	90-02	11-01	25-01	27-01	48-01	10-01	32-02	33-03	87-04	14-00
5	89-03	14-01	17-01	40-01	42-01	67-01	11-01	34-02	33-03	87-04	20-00
10	11-02	25-01	29-01	73-01	70-01	98-01	13-01	35-02	33-03	87-04	31-00
20	12-02	41-01	44-01	13-00	11-00	13-00	14-01	35-02	33-03	87-04	47-00
30	12-02	52-01	54-01	17-00	13-00	15-00	14-01	35-02	33-03	87-04	59-00
100	12-02	89-01	80-01	32-00	18-00	18-00	14-01	35-02	33-03	87-04	67-00
300	12-02	10-00	86-01	40-00	19-00	19-00	14-01	35-02	33-03	87-04	99-00
A	22-02	43-01	36-01	26-02	88-01	76-01	12-00	12-01	68-04	31-05	50-02
B	33-03	18-02	34-02	52-02	55-02	12-01	13-00	44-00	82-01	22-01	70-00
1	24-03	18-02	28-02	51-02	54-02	11-01	43-02	23-02	33-03	87-04	34-01
3	54-03	51-02	72-02	15-01	16-01	30-01	87-02	32-02	33-03	87-04	86-01
5	72-03	84-02	11-01	25-01	25-01	46-01	11-01	34-02	33-03	87-04	13-00
10	98-03	16-01	19-01	48-01	46-01	75-01	13-01	35-02	33-03	87-04	22-00
20	12-02	28-01	32-01	90-01	80-01	11-00	14-01	35-02	33-03	87-04	38-00
30	12-02	39-01	41-01	13-00	10-00	13-00	14-01	35-02	33-03	87-04	46-00
100	12-02	78-01	72-01	28-00	17-00	18-00	14-01	35-02	33-03	87-04	81-00
300	12-02	10-00	85-01	39-00	19-00	19-00	14-01	35-02	33-03	87-04	97-00

T = 9000 K

P = 100 ATM

	1	2	3	4	5	6	7	8	9	10	CVMMA
1	10-02	15-01	18-01	45-01	45-01	87-01	12-01	34-02	33-03	87-04	23 00
3	12-02	35-01	40-01	12 00	97-01	14 00	14-01	35-02	33-03	87-04	45 00
5	12-02	50-01	50-01	17 00	13 00	16 00	14-01	35-02	33-03	87-04	58 00
10	12-02	72-01	69-01	26 00	16 00	18 00	14-01	35-02	33-03	87-04	76 00
20	12-02	92-01	82-01	34 00	18 00	19 00	14-01	35-02	33-03	87-04	91 00
30	12-02	10 00	85-01	38 00	19 00	19 00	14-01	35-02	33-03	87-04	97 00
100	12-02	10 00	85-01	40 00	19 00	19 00	14-01	35-02	33-03	87-04	10 01
300	12-02	10 00	86-01	40 00	19 00	19 00	14-01	35-02	33-03	87-04	10 01
A	31-03	69 00	60 00	44 01	16 01	99 00	16-01	20-02	13-04	62-06	82 01
B	23-02	96-02	12-01	30-01	30-01	99-01	32 00	11 01	21 00	87-01	19 01
1	85-03	90-02	10-01	28-01	27-01	66-01	12-01	34-02	33-03	87-04	16 00
3	12-02	24-01	25-01	80-01	70-01	12 00	14-01	35-02	33-03	87-04	34 00
5	12-02	36-01	37-01	12 00	10 00	15 00	14-01	35-02	33-03	87-04	47 00
10	12-02	58-01	55-01	21 00	14 00	18 00	14-01	35-02	33-03	87-04	67 00
20	12-02	82-01	74-01	31 00	18 00	19 00	14-01	35-02	33-03	87-04	85 00
30	12-02	93-01	81-01	35 00	19 00	19 00	14-01	35-02	33-03	87-04	93 00
100	12-02	10 00	86-01	40 00	19 00	19 00	14-01	35-02	33-03	87-04	10 01
300	12-02	10 00	86-01	40 00	19 00	19 00	14-01	35-02	33-03	87-04	10 01